

APPLICATION NOTE

DATE:

December 1, 2018

SEVERITY:

Low

TOPIC:

Power On Sequence for G2 Firmware STA-170302

PRODUCTS AFFECTED:

G2

PROBLEM:

There is a minor usability bug in the current (but still recommended!!) G2 firmware "STA-170302".

You might encounter this in the "ADMIN-TARGETFRAME" menu when initially setting up a target; **you should not expect to see this in ordinary day-to-day shooting use.**

If you can't "activate" your targetframe (change it from "yellow" to "green", and you see a blue icon with your IP address, make sure you power on your G2 *after* your R5. If you are on the firing line and the pits are sealed, you could also reboot it remotely under software control (see following Application Note)

